

# **MAIN FEATURES**

BUILDER	SUNSEEKER	MODEL	116 YACHT
ТҮРЕ	Motor Yachts	HULL TYPE	Planing
BOAT NAME	SURVIVOR 2	YEAR	2017
INTERNA WOODS	Interior Wood Finish - Wenge Gloss Finish	CONSTRUCTION MATERIAL	Fiberglass - VTR
LOA	35.2 [m] - 115.48 [ft]	BEAM	7.33 [m] - 24.05 [ft]
DRAFT	2.39 [m] - 7.84 [ft]	ENGINES	2 x MTU 16V 2000 M96L
CRUISING SPEED	25 [kn]	MAX SPEED	19 [kn]
N° GUEST CABIN	5	N° CREW CABIN	2
N. TOILETS	5	DISPLACEMENT	140,000 [kg]
ON DISPLAY AT/IN	Alicante	COUNTRY	Spain
FLAG	Malta	ASKING PRICE	10,500,000.00 [euro]
VAT STATUS	Paid		

# **Technical information**

Engines hours	1000	
Trasmissions	Shaft Drive	
Propellers	NIBRAL	
Main generator	Kohler 70kW	
Main generator hours	1661	
Second generator	Kohler 70kW	
Second generator hours	1681	
Fuel tank	14,540 litres 5,050 litre long range overload tank	
Water tank	4,000 litres	
Grey water tank	1,225 litres	
Black water tank	1,340 litres	
Voltage	(MC5S-250A-2) 380V 50Hz - Three Phase	
Charge batteries	Yes	
Inverter	Yes	

# Description per area

# **General description**


M/Y SURVIVOR 2 is the best-priced 35M motor yacht on the market. A pedigree Sunseeker 116 Yacht with very light owners usage, low engine hours and truly exceptional crew/owner maintenance.

The main Salon and Master cabin offer full-height windows, allowing plenty of natural light to enter the interior spaces, whilst perfectly complementing the modern and elegant feel of her interior. M/Y SURVIVOR 2 accommodates up to 10 guests in her 5 staterooms with her large Master suite offering two walk-in wardrobes.

The foredeck has an emphasis on guest entertainment, including a jacuzzi situated on the bow and acres of foredeck seating, sunbathing and lounging areas. There are multiple outdoor entertaining areas throughout M/Y SURVIVOR 2, with a fold-down beach platform/club on the stern to host a number of water toys.

"M/Y SURVIVOR 2 is unquestionably one of the best kept yachts I have seen recently. Two owners from new, she has been extremely well maintained by her dedicated owner and crew. Without hesitation, I would recommend a viewing. This 35M SuperYacht is an excellent example of the Sunseeker 116 Yacht."

MICHAEL NEWTON-WOOF - Senior Broker



#### PLATINUM UPGRADE PACKAGE including:

Upgraded Anchor chain | Second pair of Mooring Bollards on Fore peak | Stainless steel Hydraulic Passerella upgrade | Side mount stairway | Teak Decking on Forepeak and Flybridge | Trailing Pumps | Auto Troll for Transmissions | Hydraulic Sleipner Stern thruster system | Fin stabilization system | Sewage Treatment plant | Air Conditioning for the Engine Room | Air Conditioning Marine Air chilled water system to Tropical specification and with quieter running WhisperCool DC fans | Diesel fuel long range overload tank of 5,050 litre capacity | Alfa Laval Fuel cleaning centrifugal separator | Tijssen CCTV camera system with eight dedicated cameras | Tijssen SMS Paging facility | Tijssen Swipe card security alarm Integrated to MPA system | Tijssen MPA Generator Control and Monitoring System Upgrade | Vimar ByMe Interior Premium Lighting System Package | Superyacht Custom Commercial Galley Refrigeration | Miele Professional Appliances upgrade - Miele Washing machine, Miele Tumble dryer and Miele dishwasher | Flybridge hardtop, including retractable centre canopy and aft extending sun canopy | Underwater lights x 15.

Built to RINA commercial rules 2013 and conformance to MCA LY3 but only issued with RINA pleasure certificates and MCA LY3 statement of compliance (private registration)

## NAVIGATION EQUIPMENT UPGRADE FOR LY3:

Measuring Log and Echo Sounder. Furuno LS6100 with console and crew mess repeater RD33 | GPS. Furuno GP170 GPS Navigator with GPS antenna | AIS. Furuno FA 150 Class A AIS Transponder with GPS and VHF antenna | Bridge Navigational Watch Alarm. Furuno BR500 | Rudder Angle Indicator. Simrad RF45X | Satellite Gyro Compass. Hemisphere GNSS V103 | Autopilot. Simrad AP70 | Magnetic Compass. A magnetic compass with 6" card | Central Navigation Display. FT Nav-vision Navigation data display with trackball and wireless keyboard | Electronic Chart System upgrades. Transas AIS, ARPA and Radar intergration.

#### COMMUNICATION EQUIPMENT UPGRADE:

MF Radio. Sailor 6310 MF/HF 150W Radio Telephone | VHF Radio. Sailor 6222 Class A VHF - DSC | VHF Radio. Simrad RS90 Class D VHF/DSc with Handsets in Wheelhouse, Fly console, Crew Mess and Emergency Steering Position | Inmarsat C with LRIT. Sailor 6110 | Navtex Receiver. Furuno NX700B | Handheld Portable VHFs. 2x Icom IC GM1600E and BP234 | EPIRB. McMurdo E5 | SART. McMurdo S4 | Furuno ultra sonic wind sensor connected to the Central Navigation Display | Iridium 9555 Satellite Phone system with docking station and external passive antenna.

## ADDITIONAL EQUIPMENT:

Bang & Olufsen audio visual upgrade as detailed in each guest area except Wheelhouse, Crew Mess and Crew Cabins.

Additional satellite decoders in the lower deck Guest Staterooms | Flybridge TV rise & fall moulding with IP rated 40" TV

Main Deck Saloon console units, Port & Stbd Dining console, forward dining console unit and TV rise and fall unit has recess to incorporate concealed low level LED rope lighting

Satellite Television System. Seatel 100 TVHD 3 Axis Global including 3 x Technomate Euro free to air HD decoders. Saloon, Master Stateroom and Crew Mess. Crew Mess decoder to be fed also to the Captains Cabin television with local control | Pre wire for possible future installation of satellite communications (Sea Tel V Sat)

TV rise and fall - Aft face decorative panel | CCTV recording facility with NVR recorder, connected to the Tijssen IP cameras and Pepwave for remote monitoring .

2 x charging sockets in the garage

Back lit signwriting on the stern | Exterior overhead lighting to be dimmable

Fore Deck Spa Tub | Valve and 2nd filling point for the Fore Deck spa bath

Removable pennant flag fitted to bell cradle structure | Teak topped lid for Fore Deck spa bath in three sections Additional AC sockets - 1 x Double Exterior Socket: Flybridge port side aft -, 1 x Double Exterior Socket: Flybridge located on the main table pedestal

Flybridge starboard side cabinet with perspex storage for exterior glassware and bottles | Flybridge - 1 x Custom double fridge drawer unit fitted in the starboard side bar

Fore Deck sail canopies fitted to wheelhouse deck seating area and main sunpad | Aft Cockpit - Additional slide in teak leaf for table with canvas bag for when not in use.

Hand bidet showers for all Guest En-suites and Day Head | Bidet Tecma toilets in Forward & Aft Guest En-suites | Bidet Tecma toilet in the Master En-suite

Octo Marine Compact Water Softener | Water Maker - Idromar Water Maker 250 litres per hour

Master en-suite outboard upstand recess in shower [stone, including stainless rail at the recess front] for the stowage of shower gels

Guest cabin and Dining area electric blinds [except en-suites] upgraded to Sonnesse 30 premium quiet motors. Controls wired to Vimar and a Somfy Telis 6 RF remotes for each cabin.

Dedicated copex installed from Technical area to hardtop with pull wires for future fitment by Client of Flir camera Medium Tinted film to side windows and sliding doors

Stern capstan winches - two Lewmar C6 400 Volt 3kW three phase vertical capstans fitted port and starboard. Capstans have dual rotation with separate controls with additional control Lewmar unit.

## 116 YACHT - SUNSEEKER

Folding stainless steel sink in the Laundry Room | Main Deck Aft Cockpit mooring bollards with stainless steel stopper eyes

Additional sound insulation around underside of spa motors [cabin side] to reduce noise transfer to master stateroom and underside of the deck head in the en-suite and master cabin.

Miele H6980P 900mm Oven | Miele DGM6800 Steam Microwave combination oven | Custom Frigoboat MS 160 fridge drawer unit in Galley w/sea water cooling, taller lower drawer G63895.

Under bed storage - lift up bed frame with gas support. No under bed drawers fitted to maximise storage in the Master, Port & Stbd double staterooms

All cabin doors with vertical grain to upper and lower panels and horizontal to middle panel with stainless trim detail. Wooden flooring Cadorin Wenge WENSPOP10 in the Main Deck Saloon, Dining and Starboard Side Entrance Lobby

Wooden flooring Cadorin Wenge WENSPOP10 in Master Stateroom with Cormar Sensations Light Taupe inset carpet | Upgraded interior stone to Gold Calacatta

Sprung mattress for Crew beds | Inboard berth moves outboard to create double berth - Forward Stbd & Port Twin Cabin

Black out Blinds for the Port Aft Guest Stateroom, the Starboard Aft Guest Stateroom, the Port Forward Guest Stateroom and the Starboard Forward Guest Stateroom.

Anchor windlass gypsys upgraded for 16mm chain. Two 165 metre lengths of 16mm high tensile galvanised chain. 2nd set stainless steel bathing ladder sockets on the Bathing Platform | Carbon fibre and polished stainless steel ensign staff suitable for 2.5 yard ensign

Portable air compressor OP20P stored in the engine room with AC 220v power supply sockets in Garage, Engine Room and Fore Deck | Kahlenberg signal timer option on lower console

Two air conditioning chilled water pumps installed and valved to allow duty/standby operation | Two raw water pumps installed and valved to allow duty/standby operation.

Tender diesel fuelling station with transfer pump from day tank and fuel hose reel | Black water IMO discharge installed at the stern.

#### 2021 REFIT WORKS:

Onyx stairs and panels | New Minotti sofa and rug on the living room area | New chairs on the dinning area | New carpet in all areas | New grey cushions in all outdoor areas | New red cushions on flybridge helm station | New red cushions on the flybridge bar stools | New red bimini on the flybridge and bow | New loose furniture on the flybridge | New stone table in the flybridge and bow area | New wood table in the outdoor dinning area | Black wrap on the hard top | New black electric Bimini on the hardtop | Black painting of the domus, radar tower and antennas | New set of red lights on the hardtop | Full polish of the hull | Hull works Anti fooling painting and anodes | Propellers maintenance including prop speed | General engine and generators maintenance | General Stabilizers maintenance | 5 years Rina Survey completed in October 2021

# Disclaimer

We offer the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. Pictures of the vessel may be taken from the catalogue. This document does not represent in any case a contractual term.