



General information/Scheda dati

Type of Ship (Tipo)	OPEN / RIB
Built (Anno costr. / imm.)	2014/2014
Builder (Cantiere) / Model (Modello)	SACS - STRIDER 15
Classification (Classifica) R.I.Na.	R.I.Na. to/al 2028
Construction material (Mat. Scafo)	VTR
L.O.A. (Lungh. f.t.)	14,20 m (46,59 ft)
Beam (Larghezza)	4,50 m (14,76 ft)
Draft (Immersione)	0,80 m (2,62 ft)
Tonnage (Stazza)	7,00 ton
Main Engines (Motori)	2 x 715HP: CUMMINS - QSM11
Engine hours (Ore di moto)	770 h on/al 06/07/2025
Drive (Trasmissione)	JOLLY DRIVE
Speed (Velocità)	47 kn (max) 39 kn (cr.)
Consumption (Consumo)	165 lt/h
Capacities (Cap. serbatoi)	1400 lt (fuel) 300 lt (fresh water)
Flag (Bandiera)/Ownership (Intestazione)	ITALIAN - PRIVATE

Asking price (Prezzo di richiesta) € 370.000,00 Vat paid

Accommodation/Interni

- Living con divano lineare in pelle con mobile contrapposto con frigorifero Vitrifrigo, forno microonde Samsung, macchina del caffè Nespresso;
- letto matrimoniale verso prua + altro letto matrimoniale a poppa;
- locale servizi separato completo di wc elettrico e doccia.
- Living area with a linear leather sofa and an opposing cabinet equipped with a Vitrifrigo refrigerator, Samsung microwave oven, and Nespresso coffee machine;
- double bed towards the bow + another double bed in the stern;
- separate service area complete with electric WC and shower.

Navigation equipment/Strumenti per la navigazione

- VHF Raymarine RAY240E;
- 2x12" Raymarine E127 multifunction display hybridtouch;
- radar + echosounder;
- autopilot Raymarine EVO-100;
- Mercury Vessel View 7 touch screen display;
- ind. angolo di barra & flaps & rudder ind. level;
- manette elettroniche - electronic throttles;
- contacatena MZ Electronic chain counter;
- elica di prua Lewmar bow thruster;

On Board Equipment/Equipaggiamento di Bordo

- Elica di prua Lewmar;
- gruppo elettrogeno ONAN 6.0MDKBJ;
- caricabatterie Victron Skylla-TG 24V/50A;
- impianto A/C Vitrifrigo;
- impianto stereo professionale (altoparlanti int/est);
- mobile bar pozzetto con lavello, vetroceramica Schott + frigo a cassetto;
- luci di cortesia + 4 luci subacquee a led;
- ancora Bruce e catena in acciaio inox; verricello salpancora Lewmar;
- impianto antincendio;
- passerella idraulica integrata nella plancia di poppa;
- boiler elettrico + doccia esterna;
- Cuscineria completa (Cuscineria di poppa e di prua);
- Bimini pozzetto completo di tendalino;
- Tendalino di poppa + chiusura consolle e cappe varie;
- dotazioni di sicurezza complete.
- Lewmar bow thruster;
- ONAN 6.0MDKBJ generator;
- Victron Skylla-TG 24V/50A battery charger;
- Vitrifrigo A/C system;
- Professional stereo system (indoor/outdoor speakers);
- Cockpit bar unit with sink, Schott glass-ceramic cooktop + drawer fridge;

- Courtesy lights + 4 underwater LED lights;
- Bruce anchor and stainless steel chain;
- Lewmar anchor windlass;
- Fire suppression system;
- Hydraulic gangway integrated into the swimming platform;
- Electric water heater + external shower;
- Complete cushions (stern and bow cushions);
- Cockpit bimini with full canopy;
- Stern canopy + console cover and various additional covers;
- Complete safety equipment.

Additional Info/Altre Informazioni

SACS STRIDER 15 in buone condizioni generali con i seguenti lavori di refitting effettuati a maggio 2024 e tutti documentabili:

- Sostituzione gruppo elettrogeno con nuovo ONAN 6.0MDKBJ;
- Sostituzione parabrezza;
- sostituzione display contacatena e sensore;
- sostituzione delle due casse esterne sotto consolle guida;
- fornitura e sostituzione n.3 scarichi a mare specchio di poppa sotto al galleggiamento con relative valvole e raccorderia in ottone;
- Fornitura e sostituzione n.2 prese a mare MM/PP con relative valvole e raccorderia in ottone;
- Fornitura e sostituzione tubi di scarico in gomma MM/PP con relative fascette inox;
- Sostituzione collettore di scarico motore Sx;
- Sostituzione tubazione estrazione aria;
- Sigillatura e pulizia piastre e bulloni trim;
- Manutenzione/ingrassatura/pulizia giunti cardanici;
- Nuovo rivestimento n°2 letti cabina di prua e cabina di poppa;
- Riverniciatura mobili neri pozzetto;
- Riverniciatura capo di banda e griglie prese d'aria sala macchine;
- Sostituzione piano calpestio interno con teak sintetico;
- Impiallacciatura dei tavoli pozzetto + nuove coperture;
- Verifica e sistemazione indicatori e pompe dei trim;
- Sistemazione "feedback" angolo di barra;
- installazione staffa di rinforzo per la passerella idraulica;
- Revisione zattera autogonfiabile e revisione estintori ed impianto antincendio sala macchine;
- Verifica e sistemazione pompa di scarico acque nere;
- Riverniciatura terminale passerella, mobile cassa lato sx e ritocchi vari mobile nero del pozzetto;
- Sostituzione luci subacquee;
- Ripristino fissaggio base tavolo sx del pozzetto;
- Verifica e ripristino aria fredda impianto A/C;
- Nuovi telecomandi passerella e sostituzione centralina;
- Nuove coperture tavoli pozzetto;
- sostituzione n.3 scarichi a mare specchio di poppa sotto al galleggiamento con relative valvole e raccorderia in ottone;
- sostituzione n.2 prese a mare MM/PP con relative valvole e raccorderia in ottone;
- sostituzione tubi di scarico in gomma MM/PP con relative fascette inox;
- Sostituzione collettore di scarico motore Sx e tubazione estrazione aria;
- Sigillatura e pulizia piastre e bulloni trim + Manutenzione/ingrassatura/pulizia giunti cardanici;

- installazione macchina caffè Nespresso.

SACS STRIDER 15 in good overall condition, with the following refitting works carried out in May 2024, all fully documented:

- Replacement of the generator with a new ONAN 6.0MDKBJ;
- Replacement of the windshield;
- replacement chain counter display and sensor;
- replacement of 2 outside speakers under console;
- Supply and replacement of 3 through-hull fittings below the waterline on the transom, including valves and brass fittings;
- Supply and replacement of 2 sea intakes (MM/PP) with related valves and brass fittings;
- Supply and replacement of rubber exhaust hoses (MM/PP) with stainless steel clamps;
- Replacement of the port engine exhaust manifold;
- Replacement of the air extraction duct;
- Sealing and cleaning of trim plates and bolts;
- Maintenance, greasing, and cleaning of cardan joints;
- New upholstery for 2 cabin beds in the forward and aft cabins;
- Repainting of black cockpit furniture;
- Repainting of the bulwark and air intake grilles for the engine room;
- Replacement of the interior flooring with synthetic teak;
- Veneering of cockpit tables + new covers;
- Inspection and adjustment of trim indicators and pumps;
- Adjustment of steering angle feedback;
- Installation of a reinforcement bracket for the hydraulic gangway;
- Overhaul of the self-inflating liferaft and inspection of fire extinguishers and engine room fire suppression system;
- Inspection and repair of the black water drainage pump;
- Repainting of the gangway tip, left-side storage cabinet, and touch-ups on the black cockpit furniture;
- Replacement of underwater lights;
- Fixing the base of the port-side cockpit table;
- Inspection and repair of the air conditioning system's cooling function;
- New remote controls for the gangway and replacement of the control unit;
- New covers for the cockpit tables;
- Installation of a Nespresso coffee machine.



























Questa specifica tecnica non è da ritenersi contrattuale. Tutte le specifiche sono fornite in buona fede a trasmesse a scopo informativo. L'azienda non garantisce né si assume alcuna responsabilità legale per la accuratezza, completezza o utilità delle informazioni. This specification is not contractual. All specifications are given in good faith and offered for informational purposes only. The company does not warrant or assume any legal liability for the accuracy, completeness, or usefulness of any information displayed.



via Lucilio 13
80132 Napoli - Italy
tel. +39 081 0143550
tel. +39 081 0140562
www.ssyachting.com
info@ssyachting.com